State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

MA

Michael O. Leavitt Governor Kathleen Clarke Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

Pa	rtial XXX Complete	Exploration
Inspection Date:	04/24/2002 / Time:	10:00 am-3:30 pm
1		pection: 03/27/2002

Mine Name: Savage Coal Terminal County: Carbon Permit Numb	er: <u>C/007/022</u>
Permittee and/or Operator's Name: Savage Industries, Inc.	
Business Address: 5250 South 300 West, Suite 200, SLC, UT 84107/PO Box	87, Wellington, UT 84542
Company Official(s): Dan Guy, Boyd Rhodes	
State Official(s): <u>Joe Helfrich</u> Federal Official(s): <u>None</u>	
Weather Conditions: Clear, sunny, 60	
Type of Mining Activity: Underground Surface XXX Prep Plan	Other
Existing Acreage: Permitted 160 Disturbed 122 RegradedS	eeded
Status: Active XXX	

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	ĪĪ	ΞĪ		\Box
3.	TOPSOIL	$\overline{[X]}$	ĹĬ	[X]	\Box
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	\Box			
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES		\Box		
d.	WATER MONITORING	Ĺ		\Box	\Box
e.	EFFLUENT LIMITATIONS				\Box
5.	EXPLOSIVES		\Box		\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES			\Box	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS				
8.	NONCOAL WASTE			\Box	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE		\Box		\Box
11.	CONTEMPORANEOUS RECLAMATION				Ц
12.	BACKFILLING AND GRADING		\Box	Ц	
13.	REVEGETATION	[X]	\Box	[X]	Ц
14.	SUBSIDENCE CONTROL				Ц
15.	CESSATION OF OPERATIONS	\Box			\sqcup
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	\Box	\Box	Ш	Ц
b.	DRAINAGE CONTROLS	\Box			Щ
17.	OTHER TRANSPORTATION FACILITIES	\Box		\Box	ĻĻ
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	\Box	\Box	Щ	
19.	AVS CHECK (4th Quarter- April, May, June)			Ц	ĻĻ
20.	AIR QUALITY PERMIT		Щ	Ц	Ļļ
21.	BONDING & INSURANCE			\sqcup	

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER:	C/007/022	DATE OF INSPECTION: 04/24/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The Topsoil Stripping amendment #02A-1 was approved on April 19, 2002. Additional requirements associated with this amendment are:

- 1. The delineated saltgrass/wetland (0.05 acres) will remain undisturbed and protected by a fence as shown on Plate 3-2 and described in a letter from Dan Guy (received April 15, 2002) until such time as the U.S. Army Corps authorizes disturbance of the 0.05 acres.
- 2. Topsoil salvage will be under the supervision of a soil scientist utilizing the topsoil thickness map created by the Spring 2002 soil survey.
- 3. The topsoil pile will be left roughened on the surface with a minimal south exposure.
- 4. Seeding of the topsoil pile that will occur immediately after roughening (not in the Fall).
- 5. Climatological information that will be submitted with the 2002 mid-term review.
- 6. Violation history information that will be submitted with the 2002 mid-term review.
- 7. Reclamation of high water table areas that will be reviewed during the 2002 mid-term review.

The midterm permit review was sent out on March 27, 2002 with the following items chosen for review:

- 1. An AVS check to ensure that Ownership and Control information is current and correct.
- 2. A review of the plan to ensure that the requirements of all permit conditions, division orders, notice of violation abatement plans, and permittee initiated plan changes are appropriately incorporated into the plan document.
- 3. A review of the applicable portions of the permit to ensure that the plan contains commitments for application of the best technology currently available (BTCA) to prevent additional contributions of suspended solids to stream flows outside of the permit area.
- 4. A review of the bond to ensure that it is in order and that the cost estimate is accurate and is escalated to the appropriate year dollars.

The Division staff is scheduled to complete their review of the Midterm items by May 15, 2002. The Topsoil Stripping requirements and Midterm Review items were discussed with Dan during this inspection.

3. TOPSOIL

Dan, Boyd, and I visited the current location of the topsoil stockpiles. We discussed stockpiling procedures to ensure minimal southern slope exposure and placement of the new topsoil on top of the reconfigured pile. Approximately 11,000 cubic yards of topsoil will be added to the existing topsoil pile. This will be a good opportunity to eliminate some of the steep slopes on the existing stockpiles. Reshaping of the pile will aid in moisture retention and provide a better vegetative cover.

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER:	C/007/022	DATE OF INSPECTION: <u>04/24/2002</u>

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Wash down water from the coal handling building is periodically discharged into sediment pond #1. In order to prevent the water from reentering the culvert, the spillway to pond 2 may have to be lowered. Dan planned to calculate the current volume of pond #2.

13. REVEGETATION

As discussed in a previous report, a better location for the reference area should be established. I provided Dan a copy of the vegetation guidelines and we discussed possible locations for a more representative reference area.

Inspector's Signature: Joseph C. Helfrick #1

Date: April 25, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM James Jensen, Savage Boyd Rhodes, Savage

Dan Guy, Blackhawk Engineering

Price Field office

 $O: \label{lem:compliance} O: \label{lem:co$